


AC MOTOR WIRING Diagram

AS-183 | 4 Wire Reversible PSC Motor



Motor connection diagram for a 4 wire reversible P.S.C. motor. Schematic shows CW rotation facing the drive end. For CCW rotation, transpose the blue and yellow leads.

AS-183 Wiring Diagram: For Groschopp 115 and 230 volt AC80, AC90, and AC100 single phase motors. May not be accurate for other brands or motor types.