


AC MOTOR WIRING Diagram

AS-184 | 3 Wire 3 Phase Motor



Motor connection diagram for a 3 wire 3 phase motor. To reverse rotation, transpose any two leads.

AS-184 Wiring Diagram: For Groschopp 230 volt AC65, AC80, AC90, and AC100 three phase motors. May not be accurate for other brands or motor types.