


AC MOTOR WIRING Diagram

AS-193 | 3 Wire Reversible PSC Motor



Motor connection diagram for a 3 wire reversible P.S.C. motor. Schematic shows CW rotation facing the drive end. For CCW rotation, move line from brown to black lead.

AS-193 Wiring Diagram: For Groschopp 115 and 230 volt AC65 single phase motors. May not be accurate for other brands or motor types.